ADDENDUM NUMBER 02

To:ALL PROSPECTIVE BIDDERSFrom:Michael Baker International, Inc.
700 Huger Street
Columbia, SC 29201Subject:Bid #2025-01 – Ace Basin Hangar Roof Repair ProjectDate:04/04/2025

This Addendum constitutes an official change to the Contract Documents and modifies the original Bid Documents entitled **Bid #2025-01 - Ace Basin Hangar Roof Repair Project** at the Lowcountry Regional Airport, as noted herein. Bidders are to acknowledge the receipt of this addendum in the space provided on the bid form. FAILURE TO DO SO MAY SUBJECT A BIDDER TO DISQUALIFICATION.

The date for receipt of bids is unchanged by this Addendum.

BIDDERS QUESTIONS:

- 1. <u>Page 10 of 17 has a list of corrective items and at the bottom of that list is "Full</u> <u>coating cost". Please clarify this. If this is an alternate to coat the entire roof in lieu</u> <u>of repairs, then we need specifications on the coating and also a space on the bid</u> <u>form for the alternate price.</u>
 - a. *MBI Response: Full Silicone Roof Re-Coating system is not included in this scope of work and shall not be included in the total Bid cost.*
- 2. <u>Discussing the project, a concern arose over the repairs to below grade drainage as</u> <u>listed on page 8 of 17 of the Assessment Report. I was informed the path to be taken</u> <u>differs from the corrective action as listed.</u> Will you please clarify any changes, if <u>any concerning the below grade drainage as described?</u>
 - a. *MBI Response: Contractors shall follow the Corrective Action for the Below Grade Drainage Attachment as described in the contract documents.*
- 3. <u>Is the coating for this roof an elastomeric or a silicone coating? In the specs it calls</u> <u>out elastomeric for joint sealants and lists manufacturers. On the coating repair it</u> <u>does not list preferred manufacturers.</u>
 - a. MBI Response: The Silicone Roof re-coating system is not a part of this scope of work. Refer to Addendum no. 1 and specification section 07 9200 Joint Sealants for information on joint and panel splice sealants.

END OF ADDENDUM NUMBER 02.